


# Endura ADA Compliant Sills


## SINGLE DOOR AND FRENCH DOOR APPLICATIONS

### Non-Thermally-Broken Sills (Inswing Only)

ADA Lite Saddle Sills




HCI5000LITE




HCI7000LITE

ADA Lite with Tileback Nosing




HCI5TILELITE




HCI7TILELITE

ADA Sills with Dam




ZHCI5002



ZHCI7002


ADA Sill with Dam and Tileback Nosing



ZHCI5TILE


## Non-Thermally-Broken Sills (Inswing Only) (CTD.)

ADA Heavy Duty Saddle Sill




HCI5000

ADA Heavy Duty Saddle Sill  
with Tileback Nosing




HCI5TILE

## Thermally-Broken Sills (Inswing and Outswing)




ZHCI4562




ZHCI5TILETB


ADA Thermally-Broken  
Inswing Sills




ZHCI5622



ZHCI7562




ZHCI7TILETB




ZHCI7562

ADA Thermally-Broken  
Outswing Sills



ZHC05622




ZHC07562


# SIDELITE AND HINGED PATIO APPLICATIONS

## Non-Thermally-Broken Sills (Inswing Only)

ADA Sills with Dam




ZHCI4562




ZHCI5622

## Thermally-Broken Sills (Inswing and Outswing)


ADA Thermally-Broken  
Inswing Sills




MZHCI4562



MZHCI5622




MZHCI6562




MZHCI7562

ADA Thermally-Broken  
Outswing Sills



MZHC05622



MZHC07562