


Endura ADA Compliant Sills


SINGLE DOOR AND FRENCH DOOR APPLICATIONS

Non-Thermally-Broken Sills (Inswing Only)

ADA Lite Saddle Sills




HCI5000LITE




HCI7000LITE

ADA Lite with Tileback Nosing




HCI5TILELITE




HCI7TILELITE

ADA Sills with Dam




ZHCI5002



ZHCI7002


ADA Sill with Dam and Tileback Nosing



ZHCI5TILE


Non-Thermally-Broken Sills (Inswing Only) (CTD.)

ADA Heavy Duty Saddle Sill




HCI5000

ADA Heavy Duty Saddle Sill
with Tileback Nosing




HCI5TILE

Thermally-Broken Sills (Inswing and Outswing)




ZHCI4562




ZHCI5TILETB


ADA Thermally-Broken
Inswing Sills




ZHCI5622



ZHCI7562




ZHCI7TILETB




ZHCI7562

ADA Thermally-Broken
Outswing Sills



ZHC05622




ZHC07562


SIDELITE AND HINGED PATIO APPLICATIONS

Non-Thermally-Broken Sills (Inswing Only)

ADA Sills with Dam




ZHCI4562




ZHCI5622

Thermally-Broken Sills (Inswing and Outswing)


ADA Thermally-Broken
Inswing Sills




MZHCI4562



MZHCI5622




MZHCI6562




MZHCI7562

ADA Thermally-Broken
Outswing Sills



MZHCO5622



MZHCO7562